



M-984-02P

Varenummer: **M-984-02P**
 Produkt beskrivelse: IC TONE DETECTOR MONOLITH 14-DIP
 RoHs Status: Blyfri / RoHS-kompatibel
 Dataark: M-984-02P.pdf

Producent / Mærke: IXYS Integrated Circuits Division
 Skib fra: Hong Kong
 Forsendelsesmåde: DHL/Fedex/TNT/UPS/EMS

SEND FORESPØRGSEL >

Billedet kan være representation.
 Se specifikationer for produktoplysninger.

Produktoplysninger

Varenummer	M-984-02P	Fabrikant	IXYS Integrated Circuits Division
Beskrivelse	IC TONE DETECTOR MONOLITH 14-DIP	Blyfri Status / RoHS Status	Blyfri / RoHS-kompatibel
Datablad	M-984-02P.pdf		
Spænding - Supply	2.7 V ~ 5.5 V	Leverandør Device Package	14-DIP
Serie	-	Emballage	Tube
Pakke / tilfælde	14-DIP (0.300", 7.62mm)	Driftstemperatur	-40°C ~ 85°C
Antal kredsløb	1	Monteringstype	Through Hole
Fugtfølsomhedsniveau (MSL)	1 (Unlimited)	Blyfri Status / RoHS Status	Lead free / RoHS Compliant
grænseflade	-	Inkluderer	-
Fungere	Tone Detector	Detaljeret beskrivelse	Telecom IC Tone Detector 14-DIP
Nuværende - Forsyning	15mA		

Relaterede produkter

<p>M-980-02T producenter: IXYS Integrated Circuits Division Beskrivelse: IC TONE DETECTOR 16SOIC Hent: M-980-02T.pdf</p> <p><input type="button" value="RFQ"/></p>	<p>M-982-02S producenter: IXYS Integrated Circuits Division Beskrivelse: IC TONE DETECTOR 20-SOIC</p> <p><input type="button" value="RFQ"/></p>
<p>M-982-02P producenter: IXYS Integrated Circuits Division Beskrivelse: IC TONE DETECTOR SPECIAL 22-DIP</p> <p><input type="button" value="RFQ"/></p>	<p>M-984-02S producenter: IXYS Integrated Circuits Division Beskrivelse: IC TONE DETECTOR MONOLITH 16SOIC Hent: M-984-02S.pdf</p> <p><input type="button" value="RFQ"/></p>
<p>M-980-02S producenter: IXYS Integrated Circuits Division Beskrivelse: IC TONE DETECTOR 3V/5V 16SOIC</p> <p><input type="button" value="RFQ"/></p>	<p>M-982-02T producenter: IXYS Integrated Circuits Division Beskrivelse: IC TONE DETECTOR 20-SOIC</p> <p><input type="button" value="RFQ"/></p>
<p>M-985 producenter: 3M Beskrivelse: EARMUFF ASSEMBLY M-985/37333 Hent: M-985.pdf</p> <p><input type="button" value="RFQ"/></p>	<p>M-985-01T producenter: IXYS Integrated Circuits Division Beskrivelse: IC TONE DETECTOR PREC 20-SOIC Hent: M-985-01T.pdf</p> <p><input type="button" value="RFQ"/></p>
<p>M-980-02P producenter: IXYS Integrated Circuits Division Beskrivelse: IC TONE DETECTOR GEN PURP 8-DIP Hent: M-980-02P.pdf</p> <p><input type="button" value="RFQ"/></p>	<p>M-984-02T producenter: IXYS Integrated Circuits Division Beskrivelse: IC TONE DETECTOR MONOLITH 16SOIC Hent: M-984-02T.pdf</p> <p><input type="button" value="RFQ"/></p>
<p>M-985-01S producenter: IXYS Integrated Circuits Division Beskrivelse: IC TONE DETECTOR PREC 20-SOIC Hent: M-985-01S.pdf</p> <p><input type="button" value="RFQ"/></p>	<p>M-985-01P producenter: IXYS Integrated Circuits Division Beskrivelse: IC TONE DETECTOR PREC 22-DIP Hent: M-985-01P.pdf</p> <p><input type="button" value="RFQ"/></p>

Relaterede tags

- IXYS Integrated Circuits Division M-984-02P
- M-984-02P-distributør
- M-984-02P Pris
- M-984-02P-billeder
- M-984-02P PDF-datablad
- M-984-02P Download datablad
- M-984-02P Lager
- Køb M-984-02P
- IXYS Integrated Circuits Division M-984-02P
- IXYS Integrated Circuits Division Leverandør
- M-984-02P leverandør
- M-984-02P-billede
- M-984-02P-datablad
- Køb IXYS Integrated Circuits Division M-984-02P
- IXYS Integrated Circuits Division-distributør